Search Notes

Application/Control No.	Applicant(s)/Patent under Reexamination
10/771,083	HOFMEISTER ET AL.
Examiner	Art Unit

2863

Toan M. Le

SEARCHED					
Class	Subclass	Date	Examiner		
702	120	5/24/2005	TL		
372	38.1,50	5/12/2005	TL		
257	688	5/20/2005	TL		
385	92-93	5/20/2005	TL .		
372	38.02	5/23/2005	TL		
Above	Updated	12/22/2005	TL		
Above	Updated	7/21/2006	TL		
398	135	7/21/2006	TL		
Above	Updated	3/3/2007	TL		
372	26,29.021	3/3/2007	TL		
398	182,186	3/3/2007	TL		
Above	Updated	8/28/2007	TL		
372	50.124	8/28/2007	TL		

ubclass	Date	
	1	Examiner

SEARCH NOT (INCLUDING SEARCH		)
	DATE	EXMR
Electrostatic Discharge Damage Photodiode Laser Switch Transceiver Pins	5/12/2005	
VCSEL Laser Driver Diode Transceiver	5/23/2005	TL
702/120; 372/38.1,38.02; 257/688; 398/135 (Laser Diode)	7/21/2006	TL
702/120; 372/26,29.021,38.1,38.02,50, 50.124; 257/688; 385/92,93; 398/135,182,186 (VCSEL Operating Reference Characteristics)	3/3/2007	TL
702/120; 372/26,29.021,38.1,38.02,50; 257/688; 385/92,93; 398/135,182,186 (VCSEL Transceiver)	8/28/2007	TL
East- See Search History Printout	8/28/2007	TL
·		